RISO, INC. **PARTS CHANGE INFORMATION**

PART: MASTER SENSOR **ISSUE #: 044**

JAPAN:TI-091

NEW PART NUMBER: 011-60005 NEW DESCRIPTION: MASTER SENSOR OLD PART NUMBER: OLD DESCRIPTION:	[ ] New [X] Modified [ ] Obsolete [ ] Other
Compatible: [X] Not Compatible: [ ] Old/Obsolete: [N]	

CHANGE REASON	MANUFACTURING CUT-IN	MODEL(S):
[ ] Cost Effective [X] Eliminate Claims [ ] Easier Operation [ ] Other	SERIAL #:	RC SERIES

The Master Sensor in the RC Product has been changed from an LED Type to an Infrared Type. Infrared Photo Sensors have proven to be more reliable with age. This change was made to enhance product reliability.

Please do not troubleshoot the absence of a light source as a problem. Infrared sensors are invisible and cannot be calibrated according to TIB # 091.

This part number is a direct replacement and is in stock.